



## DAILY VIGILANCE REPORT

In compliance of this office order dated 22.07.2024 & 21.01.2025, vigilance of the major check points/defaulters industries has been carried out by the undersigned Board Officials on 29.04.2026 during day hours.

### Details of check points checked are as under:-

S.No	Name of Identified Check Points	Flow Observed Yes/No	TDS Value	Sample Collected Yes/No	Other Remarks
1	Guwardi Drain	Yes	2800.0	No	-
2	Point near Ranjan Process	Yes	2970.0	No	-
3	Inlet point of RSWM	No	-	No	-
4	Nallah near Back Boundary wall of RSWM(Exit point of Drain into the RSWM)	No	-	No	-
5	T- Point RIICO Swaroopganj	No	-	No	-
6	Nallah at Sangam Biliya Kalan	No	-	No	-
7	Outlet of AK Spintex	No	-	No	This point was inspected in reference to complaint received through vigilance helpline no. on 29.04.2026 regarding discharge of effluent by M/s Sangam (India) Ltd. During the visit, no flow was observed.
8	Nallah near Sona Process	No	-	No	-
9	Back Side area of Sona Selection	No	-	No	-
10	Back side area of Sanwariyaji Texfab Industries and Pooja Spintex	No	-	No	-
11	Banas River- Mandapiya Stretch	No	-	No	-
12	Mangrope Anicut	No	-	No	-
13	Kothari River	No	-	No	-
14	Drain Coming from backside of M/s Sulzer & M/s Kanchan at National Highway	No	-	No	-
15	Drain Coming from backside of M/s Sulzer	No	-	No	-
16	Drain near backside corner of M/s Kanchan	No	-	No	-
17	Drain in village Chhatrikehda before joining Kothari river	No	-	No	-
18	Drain near front corner of M/s Saileela	No	-	No	-
19	Drain near M/S Ronak Processors pvt. Ltd.	No	-	No	-
20	Drain near M/S Swastik Suitings	No	-	No	-
21	Drain near M/S Rolex	No	-	No	-



S.N o	Name of Identified Check Points	Flow Observed Yes/No	TDS Value	Sample Collected Yes/No	Other Remarks
22	Back side area of M/s Samarpan Suitings	No	-	No	-

### **SPECIFIC UNIT WISE DETAILS:-**

After observing High TDS effluent at check point no -, following units were specifically inspected:

a. M/s M/s RSWM Ltd. Mandappam

During the course of Inspection following inferences were observed :-

- MEE/ATFD were found operational.
- RO Reject was found properly contained.
- RO Reject Spraying activity not observed within/outside the premises.
- Discharge of effluent was not observed through flexible lines/outlet from the unit.
- Sludge Management was satisfactory.

On the basis of observations made during inspection, site memo has not been issued to the unit.

In view of above, it is observed that non-compliance was observed, as such it is proposed to keep this vigilance report on record/forwarded to HO, if approved.

### **VIGILANCE OFFICERS**

- Jitendr Singh Meena AEE
- Kritika Somawat SO

**Vigilance Report verified by Nodal Officer:** - Sh. Mahesh Kumar Singh, Supt SO.

### **Recommendations: -**

No recommendations provided