



क्षेत्रीय कार्यालय
REGIONAL OFFICE

राजस्थान राज्य प्रदूषण नियंत्रण मण्डल, भीलवाडा

RAJASTHAN STATE POLLUTION CONTROL BOARD, BHILWARA

Email:-rorpcb.bhilwara@gmail.com

www.environment.rajasthan.gov.in



International Year
of Cooperatives

Email & Registered Post

RSPCB/RO-BHL/HOR- 06/ SP - 563

Date: 17/9/2028

M/s Samarpan Synthetics Pvt. Ltd.,
13 Km Stone, Gangapur Road, Village - Pur
Tehsil & District - Bhilwara

Subject: Regarding deficiencies observed during inspection dated 16.09.2026 concerning inadequate dispersion of industrial exhaust emissions and requirement of corrective action plan.

Reference: Inspection of your industry dated 16.09.2026.

Sir,

With reference to subject cited above, it is to inform you that your unit was inspected by the State Board officials on date 16.09.2026 and during the course of inspection, it was observed that exhaust emissions emitted through the rooftop exhaust vents/chimneys were undergoing ground-level dispersion in and around the industrial premises, indicating inadequate vertical dispersion and ineffective emission control/dispersion arrangement.

Such ground-level dispersion of exhaust emissions may adversely affect the ambient air quality in the surrounding area and may result in exposure of nearby areas to air pollutants. The observed condition indicates deficiency in the existing exhaust extraction and emission-dispersion system and requires immediate corrective measures.

The above condition is required to be rectified in accordance with the applicable provisions of the Air (Prevention and Control of Pollution) Act, 1981, particularly the requirements relating to installation, operation and maintenance of adequate air pollution control equipment and appropriate chimney/dispersion arrangements.

In view of the above-mentioned situation, the installation of a fume extraction system is deemed immediately necessary to curb emissions and ensure a safe ambient environment. Consequently, the industry is required to submit a comprehensive action plan within the next 3 days from the issue of this notice, clearly detailing the proposed corrective measures along with strict, time-bound milestones for the successful installation and commissioning of the system.

Sincerely

(Deepak Dhanetwal)
Regional Officer

18-19.पन्नाधाय सर्किल. आजादनगर. भीलवाडा
18-19, Near Pannadhaya Circle, Azad Nagar Bhilwara.

मौका पर्चा

आज दिनांक 16-03-2026 को परिवारी श्रीमान भैरुजी द्वारा राजस्थान संपर्क पर प्राप्त शिकायत क्रमांक 0926 8082 8718 66 दिनांक 15-03-2026 का मौका निरीक्षण अयोध्याद्वारकर्ता द्वारा किया गया।

मौके पर वस्तुस्थिति निम्नांकुसार है:-

- ① निरीक्षण के दौरान इकाई परिसर एवं उसके आस पास के क्षेत्र में $\text{Hazard level Dispersion}$ पाया गया। यहां दूषित वायु इकाई के Vent system से निर्गम होती हुई पायी गई।
- ② निरीक्षण के दौरान पायी गई स्थिति परिवारी द्वारा प्रस्तुत शिकायत में वर्णित तथ्यों से मेल खाती हुई पायी गई।
- ③ उक्त के क्रम में परिवारी को अवगत कराया गया कि इकाई को इस संबंध में Notice जारी किया जायेगा तथा प्रदूषित Cup के प्रभावी नियंत्रण हेतु उचित Extraction system ^{स्थापित} करने संबंधित Action plan इकाई से प्राप्त किया जायेगा।
- ④ उक्त Action plan प्रस्तुत करने हेतु इकाई को 15 दिवस का समय दिया जाना प्रस्तावित है, जिसके पश्चात् Action plan के अनुसार आवश्यक कार्यवाही एवं अनुपालन का परीक्षण किया जायेगा।

मौका पर्चा परिवारी की उपस्थिति में लिखा गया एवं मौके पर पढ़कर सुनाया गया, परिवारी ने मौके पर सभी तथ्य देखे व समझे, तथा परिवारी द्वारा संतुष्टी जतायी गयी।

भए मौका पर्चा अग्रिम कार्यवाही हेतु प्रेषित है।


J. C. Engineer
RSPCB Bhiwadi

परिवारी
भैरुजी मा2


Bhairu


JEE, RSPCB


(JEE)
RSPCB


JEE RSPCBHQ