

## COMPLAINT VERIFICATION REPORT

Date - 28.10.2025

As per the complaint received on Vigilance helpline number from Sh. Hira lal Jat & Sh. Bheru Jat, on dated 28.10.2025, regarding the disposal of effluent into agriculture field near back side of M/s Samarpan Synthetics Pvt.Ltd., Gangapur Road, Pur, Bhilwara and in compliance of directions received from Regional Officer Bhilwara, undersigned Board official visited the site and verified the complaint.

### **SUMMARY OF COMPLAINT: -**

During verification, the complainant informed that effluent was discharged from back side Gate of the aforesaid unit. Complaints agriculture field was observed situated at downstream area of back side of the unit.

### **FINDINGS OF INSPECTION: -**

During the site inspection, the following observations were made:

- 1. Accumulation of Effluent Wastewater:** Effluent was found accumulated near the backside gate of the unit. The TDS of the wastewater was measured using a Handy Hanna Meter and found to be approximately 2300 ppm. It was observed that coal stored near the coal yard area had mixed with rainwater during the night. The coal-laden runoff subsequently flowed out through the backside gate of the unit, leading to the observed accumulation of effluent.
- 2. Color of Effluent:** The effluent observed at the backside of the unit was blackish in color due to coal mixed with the rainwater.
- 3. Discharge to the Complaint Agriculture Field:** The effluent was found in the complaint agriculture field situated near the backside of the unit. The TDS of the wastewater in the complaint field was measured and found to be in the range approx. 200 - 1000 ppm.

4. **Site Observation Memo:** A Site Observation Memo was served to M/s Samarpan Synthetics Pvt. Ltd. for the observed effluent at the backside of the unit. The memo was received by Chief Engineer Sh. H.M. Pandey & was directed to rectify the reason and not repeat it in the future.

GPS tagged photographs are enclosed for ready reference.

Submitted for further necessary action, please.




(Kanhaya Lal Kumawat)

Jr. Environmental Engineer

C/s


  
(Deepak Dhanetwal)

Sr. Environmental Engineer & Regional Officer




Latitude: 25.281206  
Longitude: 74.523601  
Elevation: 437.94±8.86 m  
Accuracy: 10.18 m  
Time: 28-10-2025 13:10:42  
Note: Samarpan

NoteCam @ 105



Latitude: 25.280904  
Longitude: 74.524358  
Elevation: 437.11±10.92 m  
Accuracy: 11.15 m  
Time: 28-10-2025 13:15:17  
Note: Samarpan



Latitude: 25.280779  
Longitude: 74.525086  
Elevation: 437.62±3.28 m  
Accuracy: 4.81 m  
Time: 28-10-2025 13:21:00  
Note: Samarpan


Application Num

Service Name

Part

A. F

0





REGIONAL OFFICE  
RAJASTHAN STATE POLLUTION CONTROL BOARD  
18, Azad Nagar, Pannadhai Circle, Bhilwara - 311001

01482-241159

Date : 28/10/25

Site Observation

Ms. Sanjay Panjiwadi  
Add. Mch. P.M.  
13 E.P.I. Shanti Gangapur  
Bhilwara Distt. 311001.

Sub:- Observation during the inspection dated 28/10/25

Sir,

With reference to above, the unit was inspected on 28/10/25 and following observation was discussed.

1. you have discharged the effluent having TDS of 2250 ppm from back side of your unit gate.
2. Coal or black color water flowing in field near back side of your unit.
3. Poor house keeping found near coal yard area.
4. MEC salt bag (empty) found in open area near coal yard.

(2)

You are therefore advised to take action on the above points within 7 days and inform the action taken in the matter to the board.

Received  
J. Soni  
22/10/2025

Pandey  
28/10/2025  
Name and Designation of inspecting officer

Kanhaiya Lal Karmarkar