

Complaint verification Report

M/s Kanchan India Ltd. (Spinning)

18 Mile Stone, OppBhilwara Midway, Ajmer Road, VillageNanakpura Tehsil:Mandal
District:Bhilwara


Ref.:- 1. Telephonic complaint received on vigilance helpline no. dated 16.12.2025, regarding effluent discharge.

Content of complaint- कंचन नानकपुरा द्वारा काला पानी छोड़े जाने से नानकपुरा में स्थित भांड की बावड़ी का पानी पूर्णतः केमिकल युक्त हो गया है। जल में टीडीएस (TDS) की मात्रा लगभग 13,000 पाई गई है, जो फसलों तथा मानव स्वास्थ्य दोनों के लिए अत्यंत हानिकारक है।


Verification of the area motioned in the complaint was carried out by the Board's official dated 19.12.2025 and following observation were made-

1. Site mentioned in the complaint was visited, and the TDS of the water accumulated in the said talab was observed at various locations, ranging between 800-900 ppm.
2. No evidence of discharge of wastewater was observed in or around the pond area.
3. No wastewater discharge or spraying activity was observed within the premises or in the nearby vicinity.
4. ETP, RO and MEE of the unit was found operational at the time of visit.
5. Prima facie, based on the appearance of the accumulated water and the observed TDS values, the water appears to be rainwater.

Photograph taken during visit are enclosed.





(Jitendr Singh Meena)
Asst. Environment Engineer



Rampuriya At Payra, Rajasthan, India

Nh 48, Rampuriya At Payra, Rajasthan 311401, India
Lat 25.50803° Long 74.588024°
Friday, 19/12/2025 12:36 PM GMT +05:30



GPS Map Camera



Rampuriya At Payra, Rajasthan, India

Nh 48, Rampuriya At Payra, Rajasthan 311401, India
Lat 25.5084° Long 74.590714°
Friday, 19/12/2025 12:45 PM GMT +05:30

GPS Map Camera



Rampuriya At Payra, Rajasthan, India

Nh 48, Rampuriya At Payra, Rajasthan 311401, India
Lat 25.508033° Long 74.588022°
Friday, 19/12/2025 12:36 PM GMT +05:30

GPS Map Camera