

Complaint Inspection Report

Date of Complaint: 05.12.2025

Complaint Location: Drain behind M/s Divya Enterprises near Rto track Bhilwara

Name of Unit: Divya Enterprises (Maggi Manufacturing Unit)

According to the complainant, a drain located behind the above-mentioned unit was allegedly carrying chemically contaminated water, which was causing the death of nearby cattles gazing around it..

An on-site inspection was conducted by the undersigned on the same day of complaint. During inspection, wastewater was observed flowing into the drain located behind the aforementioned unit. The Total Dissolved Solids (TDS) level of the wastewater was measured and found to be approximately 699 ppm. Based on the observed TDS level, it indicates that no harmful or toxic chemical substances were present in the wastewater. It further suggests that no chemical effluents were being discharged into the drain by any of the industries in the vicinity. Also, unit was inspected from inside by undersigned, Notice of inspection & Site memo was issued to the unit representative regarding the shortcomings observed during inspection.

Submitted for necessary action please.


(Rohit Singh)
Jr. Environment Engineer

C/s


(Deepak Dhanetwal)
Regional Officer

