

Complaint verification Report

M/s Sangam India Ltd. (Spinning)
Post Box No.-126, Biliya Kalan, Chittorgarh Road, Bhilwara

Ref:- 1. Telephonic complaint received on vigilance helpline no. dated 02.09.2025, regarding effluent discharge.

Verification of the area motioned in the complaint was carried out by the Board's official dated 04.11.2025 and following observation were made-

1. Complainant Shri Kailash Gurjar was present during the visit. He stated that the unit is discharging industrial effluent into their solar panel area, which is further flowing into his adjoining agricultural field, due to this crop in his agricultural field has been damaged.
2. During the visit TDS of the flowing water from the solar plot was checked at the various locations and same was varies from 300 PPM to 700 PPM.
3. TDS of the complainant field was also measured and same was found approx 700 PPM.
4. No waste water discharge/spray was observed within premises and nearby vicinity.
5. No flexible pipe line was observed in the solar panel area at the time of visit.
6. Prima facie, based on the appearance and TDS of the accumulated water, it appears to be rainwater.
7. TDS of water accumulated in the solar plant area was measured at various points, and TDS of the same ranges between 400-500 PPM except one point, at this point small amount of water was accumulated having TDS approx 4500 PPM, for the same online site memo was issued to unit.

Photograph taken during visit are enclosed.


(Jitendra Singh Meena)
Asst. Environment Engineer

C/s


(Deepak Dhanetwal)
Regional Officer



